US Department of Energy Groundwater Database Groundwater Master Report

Installation Name, State: Salmon

Responsible DOE Office: Office of Legacy Management

Plume Name: Alluvial

Remediation Contractor: SM Stoller Corporation

Report Last Updated: 2009

Contaminants

Halogenated VOCs/SVOCs Present? Yes

VOC Name	Concentration (ppb)	Regulatory Driver	Cleanup Requirement
TCE	190	Yes	5
cis-1,2-DCE	130	Yes	70

Fuel Present? **No**Metals Present? **Yes**

Metal Name	Metal Concentration (ppb)	Regulatory Driver	Cleanup Requirement
As	19	Yes	10
Cr (total)	120	Yes	100
Pb	16	Yes	15

Isotopes Present? **No**Explosives Present? **Yes**Other Contaminants?**No**

Tritium Present? **Yes** Activity: **5000** (pCi/l)

Nitrates Present? **No**Sulfates Present? **No**

Hydrogeology

Conduit Flow? Yes Depth (feet): 10

Multiple Units Affected? **Yes** Avg Velocity (feet/year): **3**

Plume Information (no source)

Source **Active** Area of Plume (acres): **2**

Plume Status Plume static or shrinking in size

Remedial Approach

Remedy Name	Status	Start Date	End Date
monitored natural attenuation	Confirmed	1972	

Groundwater Use / Exit Strategy

Potable? **No**Does an Exit Strategy Exist? **No**

Sole Source Aquifer? No

Environmental Indicators (EIs)

Groundwater Migration Under Control? **Yes**Confirmed by Lead Regulator? **Yes**Confirmed by Lead Regulator? **Yes**Confirmed by Lead Regulator? **Yes**

Regulatory

Decision Document? Decision Document in Place

Date Approved **09/15/2003**

Lead Regulatory Agency: **Other** Regulatory Driver: **Other**

Regulatory Position on Groundwater Use Same as Site? No

Comments

The purpose of the groundwater montioring program at the Salmon site is to monitor radionuclide leakage from the salt dome cavity created by detonation of a nuclear device 2,710 feet below ground surface. Non-radiological VOCs and metals are fugitive contamination from a mudpit and rat hole. The arsenic detected is not traceable to DOE (or predecessor agency) activities.